


DOUGHNUT MACHINES

G SPARE PART LIST-EXPLODING DRAWING



FTDME13

DOUGHNUT MACHINES

G SPARE PART LIST-EXPLODING DRAWING

PRODUCT CODE: FTDME13		
NO	PRODUCT NAME	P.CODE
1	SCREW	Y.LK.003.001
2	TOP GLASS	Y.LK.003.002
3	LAMP HOLDER	Y.LK.003.003
4	LEFT SIDE GLASS	Y.LK.003.004
5	GLASS HOLDER	Y.LK.003.005
6	BOWL	Y.LK.003.006
7	PLEYT	Y.LK.003.007
8	0-6 SWITCH	Y.LK.003.008
9	WARNING LAMP	Y.LK.003.009
10	SWITCH BUTTON	Y.LK.003.010
11	SWITCH (ON-OFF)	Y.LK.003.011
12	SCREW LID	Y.LK.003.012
13	WHEEL WITH BREAK	Y.LK.003.013
14	PIPE	Y.LK.003.014
15	FRONT GLASS	Y.LK.003.015
16	LED	Y.LK.003.016
17	VESSEL	Y.LK.003.017
18	BASE FRAME	Y.LK.003.018
19	NON-BREAK WHEEL	Y.LK.003.019
20	20 AMP POWER SUPPLY	Y.LK.003.020
21	RIGHT SIDE GLASS	Y.LK.003.021
22	HOLDER PIPE CONNECTION PART	Y.LK.003.022