


G SPARE PART LIST-EXPLODING DRAWING



MEAT MINCERS

G SPARE PART LIST-EXPLODING DRAWING

NO	PRODUCT NAME	
1	BASE FRAME	
2	FEET	
3	URGENT STOP	
4	BUTTON (FORWARD-BACKWARD)	
5	BUTTON (START-STOP)	
6	FAN	
7	CONTACTOR (DILEM10)	
8	AUXILIARY CONTACTOR	
9	MICA SHEET METAL	
10	SPILLAGE TRAY	
11	PESTLE	
12	HINGE	
13	SAFETY GUARD	
14	SAFETY GUARD PIN	
15	LID	
16	NUT	
17	DISC	
18	BLADE	
19	SPIRAL	
20	MEAT TUBE	
21	SEAL (30X50X7)	
22	BALL BEARING (51106)	
23	LOCK BALL TEAM	
24	BRACKET	
25	LOCK SHEET METAL	
26	MOTOR SHAFT	
27	BALL BEARING (6906)	
28	REDUCER	
29	MOTOR	
30	ORING	
31	MOTOR CONNECTION SHAFT	
32	SEGMAN 471-23	
33	BRACKET FLANGE	
34	SPIRAL SCREW	