


MEAT MINCERS

G SPARE PART LIST-EXPLODING DRAWING



G SPARE PART LIST-EXPLODING DRAWING

NO	PRODUCT NAME	
1	BASE FRAME	
2	BRACKET	
3	SPILLAGE TRAY	
4	PESTLE	
5	SAFETY GUARD	
6	FEET	
7	SWITCH	
8	MEAT TUBE	
9	SPIRAL	
10	MEAT TUBE NUT	
11	DISC	
12	BLADE	
13	SPIRAL SCREW	
14	START-STOP BUTTON	
15	SHAFT	
16	SEAL 63X85X10	
17	BALL BEARING 6009	
18	BALL BEARING 51209	
19	URGENT STOP	
20	BALL BEARING 6204	
21	LOCK SHEETMETAL	
22	ORING	
23	WICK	
24	SAFETY GUARD PIN	
25	MOTOR	
26	LUBRICANT INDICATOR	
27	REDUCER LID	
28	SLEEVE	
29	BRACKET FLANGE	
30	REDUCER CONNECTION FLANGE	
31	REDUCER BODY	
32	LOCK GROUP	
33	CONTACTOR DILEM10	
34	SEAL 25X40X8	
35	SEGMAN	
36	SMALL BEARING BLOCK GEAR	
37	PLASTIC BEARING BLOCK GEAR	
38	SHAFT GEAR	
39	MOTOR GEAR	
40	STOPPLE	